PAGE: 1 PRINT DATE: 05/11/94

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CRITICAL HARDWARE NUMBER: 03-1-0408-X

SUBSYSTEM NAME: MAIN PROPULSION

		REVISION:	1	5/11/94	
	PART NAME VENDOR NAME		PART NUMBER VENDOR NUMBER		
LRU	: DISCONNECT, LO2, 17 INCH	MC2	84-0389	-0551 (ORB HALF)	
LRU	DISCONNECT, LO2, 17 INCH	MC2	MC284-0389-0552 (ET HALF)		
	PART D	ATA			

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS: DISCONNECT, LO2 FEED, 17 INCH, ORBITER & ET HALF. (PD1)

QUANTITY OF LIKE ITEMS: 1 ONE

FUNCTION:

ET/ORBITER FEED LINE DISCONNECT PROVIDES LO2 PROPELLANT TO THE MPS AND A MEANS OF LOADING AND DETANKING THE ET. EACH DISCONNECT HALF CONTAINS A PNEUMATICALLY ACTUATED FLAPPER CLOSURE DEVICE WHICH REMAINS IN ITS LAST ACTUATED POSITION (BISTABLE). THE VALVES ARE CLOSED AFTER MECO TO PREVENT PROPULSIVE VENTING LEADING TO ET/ORBITER RECONTACT, TILE/DOOR DAMAGE DUE TO EXPOSURE TO PROPELLANTS, LOSS OF HELIUM SUPPLY DURING MANIFOLD REPRESSURIZATION (RTLS/TAL ABORT CRITICAL), AND SYSTEM CONTAMINATION DURING ENTRY. DURING UMBILICAL SEPARATION, THE VALVE SYSTEM IS DESIGNED TO MECHANICALLY CLOSE BOTH THE ORBITER AND ET DISCONNECT FLAPPERS IF UNABLE TO CLOSE THEM PNEUMATICALLY (POST MECO). REDUNDANT OPEN AND CLOSE (TWO EACH) VALVE POSITION SWITCHES ARE LOCATED ON THE ORBITER HALF OF THE DISCONNECT. THE FLAPPER DRIVE. MECHANISM IS DESIGNED TO ALLOW RELIEF OF PROPELLANTS TRAPPED BETWEEN THE FLAPPERS AFTER DISCONNECT CLOSURE.

A PNEUMATICALLY ACTUATED LATCH MECHANISM IS PROVIDED TO PREVENT THE VALVE FLAPPERS FROM CLOSING DURING FLOW CONDITIONS. THE LATCH IS BISTABLE AND IS CONTROLLED BY A SEPARATE PNEUMATIC ACTUATOR ASSEMBLY WITH REDUNDANT LOCK AND UNLOCK (TWO EACH) POSITION SWITCHES. LATCH MECHANISM INCORPORATES A TOGGLE PIVOT WHICH ALLOWS FLAPPER CLOSURE DURING BACK UP MECHANICAL SEPARATION WITH LATCH IN LOCKED POSITION. SEE LATCH FMEA/CIL 0454 FOR ADDITIONAL INFORMATION.

SUBSYSTEM : MAIN PROPULSION

FMEA NO:03-1 -0408 -7 REV:02/19/

ASSEMBLY

P/N RI :MC284-0389-XXXX CRIT. FUNC: CRIT. HDW:

ORB HALF 0551 ET HALF 0552

P/N VENDOR:

VEHICLE EFFECTIVITY: 102 103

QUANTITY :1 :ONE

Х X

PHASE(S): PL

REDUNDANCY SCREEN:

LO X OO DO

PREPARED BY:

APPROVED BY:

A-В-

DES REL

J E OSLUND L H FINEBERG

DES

APPROVED BY (NO SSM/~

QΕ

E M GUTIERREZ

REL QE (4

ITEM:

DISCONNECT, LO2 FEED (WITH LATCH) 17 INCH, ORBITER 6 ET HALF. (PDI)

FUNCTION

ET/ORBITER FEED LINE DISCONNECT PROVIDES LO2 PROPELIANT TO THE MPS AND MEANS OF LOADING AND DETANKING THE ET. EACH DISCONNECT HALF CONTAINS : PNEUMATICALLY ACTUATED FLAPPER CLOSURE DEVICE WHICH REMAINS IN ITS LAST ACTUATED FOSITION (BISTABLE). THE VALVES ARE CLOSED AFTER MECO TO PREVENT PROPULSIVE VENTING LEADING TO ET/ORBITER RECONTACT, TILE/DOOR DAMAGE DUE TO EXPOSURE TO PROPELLANTS, LOSS OF HELIUM SUPPLY DURING MANIFOLD REPRESSURIZATION (RTLS/TAL ABORT CRITICAL), AND SYSTEM CONTAMINATION DURING ENTRY. DURING UMBILICAL SEPARATION, THE VALVE SYSTEM IS DESIGNED TO MECHANICALLY CLOSE BOTH THE ORBITER AND ET DISCONNECT PLAPPERS IF UNABLE TO CLOSE THEM PNEUMATICALLY (POST MECO). REDUNDANT OPEN AND CLOSE (TWO EACH) VALVE POSITION SWITCHES ARE LOCATED ON THE ORBITER HALF OF THE DISCONNECT. THE PLAPPER DRIVE MECHANISM IS DESIGNED TO ALLOW RELIEF OF PROPELLANTS TRAPPED BETWEEN THE FLAPPERS AFTER DISCONNECT CLOSURE.

A PNEUMATICALLY ACTUATED LATCH MECHANISM IS PROVIDED TO PREVENT THE VAL FLAPPERS FROM CLOSING DURING FLOW CONDITIONS. THE LATCH IS BISTABLE AN IS CONTROLLED BY A SEPARATE PNEUMATIC ACTUATOR ASSEMBLY WITH REDUNDANT LOCK AND UNLOCK (TWO EACH) POSITION SWITCHES. LATCH MECHANISM INCORPORATES A TOGGLE PIVOT WHICH ALLOWS FLAPPER CLOSURE DURING BACK UP MECHANICAL SEPARATION WITH LATCH IN LOCKED POSITION. SEE LATCH FMEA/CI 0454 FOR ADDITIONAL INFORMATION.

FAILURE MODE

FAILS TO REMAIN CLOSED (ORBITER AND/OR ET FLAPPERS) FOLLOWING ORBITER/ET UMBILICAL SEPARATION

CAUSE(S)

PIECE PART STRUCTURAL PAILURE

SUBSYSTEM :MAIN PROPULSION FMEA NO:03-1 -0408 -7 REV:02/19/88

EFFECT(S): ON

(A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) GREW/VEHICLE:

(A,B)

- CASE I ORBITER FLAPPER FAILS TO REMAIN CLOSED FOLLOWING ORBITER/ET UMBILICAL SEPARATION. RESULTS IN POSSIBLE TILE AND DOOR DAMAGE AT THE UMBILICAL AREA DUE TO CRYO EXPOSURE. FOR RTLS AND TAL ABORTS, RESIDUAL LOZ WILL ENTER THE AFT COMPARTMENT CAUSING POSSIBLE AFT COMPARTMENT OVERPRESSURIZATION AND FIRE/EXPLOSION HAZARD. ALSO RESULTS IN LOSS OF HELIUM SUPPLY DURING MANIFOLD REPRESS CAUSING LOSS OF AFT COMPARTMENT PURGE (RTLS AND TAL ABORT CRITICAL).
- CASE II ET FLAPPER FAILS TO REMAIN CLOSED FOLLOWING ORBITER/ET UMBILICAL SEPARATION. RESULTS IN POSSIBLE TILE AND DOOR DAMAGE AT THE UMBILICAL AREA DUE TO CRYO EXPOSURE AND ORBITER/ET RECONTACT DUE TO PROPULSIVE VENTING FOLLOWING ET STRUCTURAL SEPARATION. ALSO MAY RESULT IN ET IMPACT OUTSIDE ALLOWABLE FOOTPRINT.
- (C.D) POSSIBLE LOSS OF CREW/VEHICLE/LIFE/PROPERTY.
- DISPOSITION & RATIONALE:

 (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY (E) OPERATIONAL USE:
- (A) DESIGN
 ONCE THE FLAPPERS HAVE BEEN CLOSED, THE FOLLOWER ARM TORSION BARS AND SYSTEM INTERNAL PRESSURE PROVIDE THE FORCE NECESSARY TO MAINTAIN THE FLAPPERS IN THE CLOSED POSITION.

DESIGN FACTORS OF SAFETY FOR INTERNAL PRESSURE ARE 1.3 PROOF, 1.5 BURST FOR THE DISCONNECT. THE ORBITER FLAPPERS HAVE A MINIMUM USEFUL LIFE OF 3500 CYCLES WHICH IS EQUIVALENT TO 100 ORBITER MISSIONS. THE ET FLAPPERS HAVE A MINIMUM LIFE OF 150 CYCLES WHICH IS EQUIVALENT TO ONE ORBITER MISSION. STRUCTURAL ANALYSIS INDICATES POSITIVE MARGINS OF SAFETY FOR ALL CONDITIONS OF VALVE OPERATION; PRACTURE/PATIGUE ANALYSIS SHOW THAT ALL CRITICAL PARTS ARE SATISFACTORY FOR FOUR TIMES EXPECTED LIFE (ET ONE MISSION, ORBITER - 100 MISSIONS).

THE DISCONNECT VALVE CONSISTS OF COMPONENTS MANUFACTURED FROM 2024-T651 AL ALLOY (FLAPPER ASSEMBLY), INCONEL 718 (ARM FOLLOWER) AND A286 CRES (ARM DRIVE ASSEMBLY). THE VALVE HOUSING IS MANUFACTURED FROM 2219 AL ALLOY. THE FLAPPER FLEX SEAL IS MADE OF INCONEL 718 WITH A TEFLON COATING, AND THE SEAL SEAT IS MADE OF A286 CRES.

SUBSYSTEM : MAIN PROPULSION FMEA NO: 03-1 -0408 -7 REV: 02/19

(B) TEST

ATP (ACTUATOR)

and the second control of the second control

PROOF: AMBIENT, 1275 PSIG

OPERATIONAL (TWO CYCLES): AMBIENT; 400, 740, 780 PSIG

RESPONSE TIME (OPENING/CLOSING): ROOM AMBIENT/-300 DEG F

RESPONSE TIME AT 400, 700 AND 780 PST

LEAKAGE: EXTERNAL AND INTERNAL, AMBIENT AND CRYO

ATP - ET/ORBITER MATED DISCONNECT ASSEMBLY

FLAPFER ANGLE: ET 4.5 +/- 0.25 DEG, ORB 3.0 +/- 0.25 DEG

TIP LOAD: ET 55 LB MINIMUM, ORE 40 LB MINIMUM

POSITION SWITCH VERIFICATION: LATCH IN LOCKED POSITION. ROTATION FRO FLAPPER POSITION OF REST ON DOWNSTRIKE SURFACE TO FLAPPER POSITION WHERE OPEN INDICATOR LIGHT TURNS ON MUST BE 4 DEG, MINIMUM.

PROOF: AMBIENT, 1275 PSIG, ACTUATOR
286 PSIG FOR ORBITER CLOSURE DEVICE
58 PSIG FOR ET CLOSURE DEVICE

OFERATIONAL CYCLE: CRYO, -300 DEG F, ACTUATOR PRESSURE 740 PSIG FOR 8 CYCLES AND 450 PSIG FOR 5 CYCLES AMBIENT, He AT 400 PSIG (1 CYCLE) AND 740 PSIG (5 CYCLES)

CLEANLINESS VERIFICATION: MOISTURE FREE AND CLEANED TO LEVEL 400A OF MA 0110-301

LEAKAGE: EXTERNAL

VALVE: LN2/AMBIENT TEMPS: 50 SCIMS OF GHE AT 10 PSIG,
SCIMS OF GHE AT 50 PSIG; LATCH SHAFT SEAL, 80 SCIMS
GHE; 150 SCIMS OF GN2 AT 185 PSIG; LATCH SHAFT SEAL
80 SCIMS OF GN2
VALVE ACTUATOR:

CRYO (BODY TEMP AT -300 DEG F, ACTUATOR AT -200 DEG F)/AMBIENT TEMPS: 100 SCIMS OF GHE AT 740 PSI

SUBSYSTEM : MAIN PROPULSION FMEA NO:03-1 -0408 -7 REV:02/19/88

والمتعارض والمراجع المتعارض والمتعارض والمتعار

INTERNAL

VALVE: AMBIENT TEMPS: 1000 TO 2000 SCIMS OF GHE AT 1 TO 15 PSIG; 2500 SCIMS OF GN2 AT 200 PSIG LN2 TEMPS: 2500 SCIMS OF GHE AT 60 PSIG; 2500

SCIMS OF GN2 AT 200 PSIG

VALVE ACTUATOR:

CRYC (BODY TEMP AT -300 DEG F, ACTUATOR AT -200 TO O DEG F)/AMBIENT TEMPS: 100 SCIMS OF GHE AT 740 PSIG

RELIEF OFERATION: -300 DEG F, CRACKING/RESEAT PRESSURE, 0.1-5 PSID (ET ONLY)

ELECTRICAL CHARACTERISTICS (INSULATION RESISTANCE AND VOLTAGE DROP), AND DIELECTRIC STRENGTH

FLOW LINER - ROUNDNESS VERIFICATION (FREE END EIGHT POINTS MEASUREMENT)

CERTIFICATION

COMPONENT QUALIFICATION (INCLUDES TESTING FROM PREVIOUS CONFIGURATION ------ WITHOUT LATCH)

SALT FOG

VIBRATION - THREE AXES:

SINUSOIDAL: 5 TO 35 HZ AT 0.25 G, ZERO TO PEAK

RANDOM: 20 TO 2,000 HZ 5.7 G RMS FOR X-AXIS, 5.2 G RMS FOR Y AND Z-AXIS, NO FLOW (LN2), FLAPPERS OPEN, LATCH ENGAGED

> THE DISCONNECT IS CHILLED WITH LN2 AND STABILIZED AT -300 DEG F. 10 PSIG DISCONNECT, 740 PSIG ACTUATOR. THESE CONDITIONS ARE MAINTAINED THROUGHOUT SINUSOIDAL AND RANDOM VIBRATION. ACTUATOR VENTED DURING LAST TWO MINUTES OF VIBRATION.

THERMAL CYCLE: =400 TO 150 DEG F, 3 CYCLES

OPERATING LIFE: AMBIENT, 740 PSIG HE FOR A TOTAL OF 2,400 CYCLES FOR ORBITER AND 100 CYCLES FOR ET. THE RELIEF MECHANISM WAS CYCLED DURING ET VALVE CYCLING.

> CRYO, 740 PSIG HE, -400 DEG F FOR A TOTAL OF 1000 CYCLES FOR ORBITER AND 50 CYCLES FOR THE ET. THE RELIEF MECHANISM WAS CYCLED DURING ET VALVE CYCLING.

ELECTRICAL CHARACTERISTICS (INSULATION RESISTANCE AND VOLTAGE DROP)

SUBSYSTEM : MAIN PROPULSION FMEA NO:03-1 -0408 -7 REV:02/19/:

LEAKAGE: EXTERNAL AND INTERNAL, AMBIENT AND CRYO

ENGAGE - DISENGAGE: ENGAGE FORCE = 1,000 LBS MAX, DISENGAGE
FORCE = 6,000 LBS MAX

BURST TEST: PNEUMATIC ACTUATOR, 1700 PSIG HYDROSTATIC PRESSURE FOR 2 MINUTES

TYPE I AND TYPE II MATED (OPEN POSITION) 450 PSIG HYDROSTA1 PRESSURE FOR 2 MINUTES

TYPE I AND TYPE II DEMATED (CLOSED POSITION) 330 PSID TO TYPE I, 68 PSID TO TYPE II FOR 2 MINUTES

UMBILICAL SEPARATION TEST: (WITHOUT LATCH)

THE DISCONNECT WAS INSTALLED IN THE UMBILICAL ASSEMBLY DURING THE SEPARATION TEST PROGRAM. THE UMBILICAL ASSEMBLY WAS SUBJECTED TO RANDOM VIBRATION TESTS (4.4 HOURS PER AXIS) WHILE FILLED WITH LN2. THE DISCONNECT WAS ALSO SUBJECTED TO UMBILICAL RETRACT TESTS AT BOTH NOMINAL CONDITIONS AND SIMULATED HYDRAULIC RETRACT ACTUATOR FAILURES.

UMBILICAL SEPARATION TEST: (WITH LATCH)

FLAPPER FNEUMATICS/LATCH PNEUMATICS/PYROS/RETRACTOR HYDRAULICS

- (1) PNEUMATIC CLOSURE (NORMAL) 4 CYCLES
- (2) MECHANICAL CLOSURE (BACKUP) 5 CYCLES

BOTH PERFORMED AT AMBIENT, LN2 AND LH2 CONDITIONS.

FLOW LINER WATER FLOW TESTS:

DESIGN FLOW TO 19,600 GPM ALLOWABLE DELTA P IS 10 PSID AT THE LINER

TO DETERMINE THE STABILITY OF THE FLOW LINER. THE FLOW TUBE HAD NO PERMANENT DAMAGE AFTER BEING SUBJECTED TO WATER FLOWS UP TO 20,000 GP (TEST TIME OF 2 MINUTES / 6 RUNS MINIMUM). AFTER VERIFYING PERFORMANCE AT 20,000 GPM, THE UNIT WAS SUBJECTED TO 22,700 GPM TO VERIFY DESIGN MARGIN (NO PERMANENT DAMAGE).

FMEA NO:03-1 -0408 -7 REV:02/19/88 SUBSYSTEM : MAIN PROPULSION

the second secon

FLAPPER ANGLE STABILITY MARGIN WATER FLOW TESTS:

FOURTEEN (14) EXPLORATORY TEST SERIES (FLOW 4,000 TO 20,800 GPM) E.T. FLAPPER SETTING VARYING FROM 1.6 TO 5.8 DEG. ORB. FLAPPER SETTING VARYING FROM 0.9 TO 5.4 DEG.

CERTIFICATION TEST RUN AT WORST CASE PRODUCTION SETTING (FLOW RANGE TO 109% POWER LEVEL).

PROOF TEST SERIES - MAXIMUM FLOW 22,700 GPM, AT ANGLES BELOW MINIMUM FLIGHT SETTINGS

PRODUCTION ANGLE SETTINGS E.T. 4.5 +/- 0.25 DEG ORB. 3.0 +/- 0.25 DEG

FLAPPER TIP LOAD MARGIN WATER FLOW TEST:

EIGHT (8) EXPLORATORY TEST SERIES (FLOW RANGE TO 109% POWER LEVEL)

FLOW 4,000 TO 20,500 GPM

ORBITER: 3.0 +/- 0.1 DEG FOR SEVEN SERIES, 4.1 +/- 0.1 FOR ONE SERIES TIP LOAD RANGE: 20 TO 62 LBS

ET: 3.95 +/- 0.1 DEG

TIP LOAD RANGE: 23 TO 61 LBS

RECOMMENDED TIP LOAD:

ORBITER: 40 LBS MINIMUM 55 LBS MINIMUM

LATCH WATER FLOW TESTS:

TWENTY-FOUR (24) EXPLORATORY TEST SERIES (FLOW 4,000 TO 22,100 GPM)

CERTIFICATION TEST RUN AT MINIMUM PRODUCTION SETTING (FLOW RANGE TO 109% POWER LEVEL).

TWO TEST SERIES IN FILL DIRECTION (FLOW 4,000 TO 6,400 GPM), LATCH PNEUMATIC PRESSURE VENTED (BISTABILITY)

PROOF TEST - 23,200 GPM

the second control of the second of the seco

SUBSYSTEM : MAIN PROPULSION FMEA NO:03-1 -0408 -7 REV:02/19

LATCH CRYO FLOW TESTS:

SIXTEEN (16) TESTS WITH LN2/LO2 (FLOWS VARY FROM ONE ENGINE AT 65% THREE AT 109%):

DISCONNECT FLAPPER STABILITY/LOADS

CAVITATION

FRICTION PRESSURE LOSS

ENGINE CUTOFF SENSOR RESPONSE

STEADY STATE TEST: LN2 (65% AND 109% OF RATED POWER LEVEL), L ENGAGED. LO2 (100%, 104% AND 109% OF RATE POWER LEVEL), LATCH ENGAGED AND NOT ENGAGED.

TERMINAL DRAIN: (SATURATED LO2) (65% AND 109%) LATCH ENGAGED NOT ENGAGED.

OMRSD

V41AYO.010 LO2 EXTERNAL LEAK TEST (I5)

V41AYO.130 LO2 DECAY TEST (EVERY FLT)

V41AYO.221 HELIUM SIGNATURE TEST (EVERY FLT)

V41AYO.260 LO2 SHAFT SEAL LEAK CHECK (I5)

V41880.080 LO2 SEAT LEAKAGE TEST (EVERY FLT)

V41BIG.240 ORB/ET DISC RESPONSE TIME (POST FLT DATA ANALYSIS)

V418UO.280 DISCONNECT FLAFFER ANGLE VERIFICATION (EVERY FLT)

V41BUO.320 DISCONNECT INSPECTION AND TIP LOAD VERIF (EVERY FLT)

V41BUO.330 MPS COMPONENT CAVITY INSPECTION (EVERY FLT)

V41BUO.370 ORB/ET DISC PREPARATION FOR OPP ROLLOUT (EVERY FLT)

V41BVO.020 MPS ORB/ET DISC CLEANING (EVERY FLT)

V41BVO.030 ORB/ET UMBILICAL DISC AND SEAL INSPECTION (EVERY FLT)

T41FUN.040 OPENING TORQUE BEFORE MATING (EVERY FLT)

T41FUN.061 ET 17" TIP LOAD/FLAPPER ANGLE INSPECTION (EVERY FLT)

T41QAL.090 LO2/LH2 17" DISCONNECT INSPECTION (EVERY FLT)

T41QAL.100 LO2/LH2 17" DISCONNECT CLEANING (EVERY FLT)

SOOHCO.400 VERITY ET/ORB DISC POSITIONS (PRIOR TO MATING) (EVERY FLT

S00000.090 PD1 RESPONSE TIME (MATED) (EVERY FLT)

(C) INSPECTION

RECEIVING INSPECTION

RAW MATERIALS ARE VERIFIED BY INSPECTION FOR MATERIAL AND FROCESS CERTIFICATION. ALL MACHINED ITEMS ARE DIMENSIONALLY INSPECTED AND VERIFIED (MIL-STD-105). CHEMICAL/MECHANICAL PROPERTIES AND RECORDS RECEIVED MATERIALS ARE RETAINED FOR VERIFICATION. BODY FORGING IS ULTRASONICALLY AND DYE PENETRANT INSPECTED.

the second of the second

SUBSYSTEM : MAIN PROPULSION FMEA NO:03-1 -0408 -7 REV:02/19/88

CONTAMINATION CONTROL

CLEANLINESS LEVEL TO 400A VIA FREON FLUSH AND SAMPLE VERIFIED. ALL SEAL GROOVES ARE INSPECTED FOR CLEANLINESS AND EVIDENCE OF DAMAGE.

ASSEMBLY/INSTALLATION

THREADED INSERTS AND CRITICAL DIMENSIONS VERIFIED BY INSPECTION. SEALING SURFACES ARE VISUALLY INSPECTED FOR DEFECTS. REPAIRED AND REWORKED ITEMS ARE DIMENSIONALLY CHECKED. LOG OF CLEAN ROOM VERIFIED. ALL ENGINEERING-DEFINED FEATURES AND SURFACE FINISHES AND TORQUE REQUIREMENTS ARE COMPLETELY INSPECTED AND VERIFIED.

THE PRIMARY INTERFACE SEAL IS CHECKED FOR ID, OD AND ROUNDNESS. ALL DIMENSIONS DEFINED IN DRAWING ARE VERIFIED BY INSPECTION.

CRITICAL PROCESSES

HEAT TREATMENT AND PART PASSIVATION ARE VERIFIED BY INSPECTION.

NON-DESTRUCTIVE EVALUATION

PARTS ARE RADIOGRAPHICALLY AND DYE PENETRANT INSPECTED AS IMPOSED BY ENGINEERING IN THE DRAWING REQUIREMENTS.

TESTING

ATP AND TEST MEASUREMENT EQUIPMENT CALIBRATION VERIFIED BY INSPECTION.

HANDLING/PACKAGING

PACKAGING FOR SHIPMENT VERIFIED BY INSPECTION.

(D) FAILURE HISTORY

SEVERAL INTERNAL LEAK ATP FAILURES HAVE OCCURRED WHICH WERE SLIGHTLY OVER SPECIFICATION LIMITS OF 1000 SCIM AT LOW PRESSURE (REFERENCE CARS A6936, A6858, A5352, AND AB3730). THE UNITS WERE MADE ACCEPTABLE BY INCREASING THE ACCEPTABLE PROCUREMENT SPECIFICATION LEAKAGE RATE TO 2,000 SCIM MAXIMUM.

DURING THE ATP OF AN LOZ ORBITER DISCONNECT THE FLAPPER EXHIBITED EXCESSIVE LEAKAGE AT LOW PRESSURE CRYC CONDITIONS (REFERENCE CAR AD3440). LEAKAGE WAS 2,099 SCIM, MAX ALLOWABLE 1,000 SCIM. LEAKAGE AT ALL HIGH PRESSURE CONDITIONS WERE WITHIN SPECIFICATION REQUIREMENTS. UNIT WAS ACCEPTED BY WAITER SINCE LEAKAGE AT THE LOW PRESSURE CONDITION IS CONSIDERED ACCEPTABLE.

IMPROPERLY INSTALLED SEAL DISCS ON FOUR DIFFERENT FLAPPERS CAUSED AN EXCESSIVE INTERNAL LEAKAGE DURING ATP (REFERENCE CAR'S AB8349, AC1997, AC4883 AND AD0131) THE ASSEMBLY FIXTURE HAS BEEN MODIFIED TO INSURE CENTERING OF THE SEAL DISC DURING SHRINK RING INSTALLATION.

(E) OPERATIONAL USE

NO CREW ACTION WILL BE TAKEN.